



Figure 1: Management Unit 23 (Fairlight Glen)

 Blue: Recycling Extraction Point
 Red: Recycling Deposition Area

Fairlight Glen is an area of high geological importance, however with no cliff top infrastructure or residential properties this section of coast remains undefended. The eastern section is characterised by high cliffs varying Ashdown sandstone and Wadhurst Clay, towards the west.

The Management Policy for the next 100 years is to maintain a 'No Active Intervention' approach.

No recycling or coastal maintenance has been undertaken here.

Survey Regime

Survey type	Frequency	Profile spacing/survey extent
Topographic baseline	1 per Phase	50m to MLWS
Topographic interim profile	Spring and Autumn	150m to MLWS
Bathymetry	5 years	50m profiles to 1km offshore
Ortho-photography	5 years	MLW
Aerial photography	Ceased in 2008	MLW
Lidar	Rolling Programme	MLW
Habitat Mapping	5 Years	As Required

Full details of data availability and extents can be found on the Channel Coast Observatory Website (www.channelcoast.org)

Summary of Beach Operations

Date	Operation	Quantity (m ³)	Location/Notes
No beach material has been recycled since 2003			

Full details of beach operations can be obtained from Canterbury City Council (strategic.monitoring@canterbury.gov.uk)